

Oil Field Environmental Incident Summary

Incident: 20161029010536 **Date/Time of Notice:** 10/29/2016 01:05
Responsible Party: ENERPLUS RESOURCES USA CORPORATION
Well Operator: ENERPLUS RESOURCES USA CORPORATION
Well Name: TACKLE 149-95-36C-25H TF
Field Name: EAGLE NEST **Well File #:** 31072
Date Incident: 10/28/2016 **Time Incident:** 06:00 **Facility ID Number:**
County: MCKENZIE **Twp:** 149 **Rng:** 95 **Sec:** 36 **Qtr:**
Location Description: Fire affected 2' X 15' area outside of lease boundary.

Submitted By: Tony Lucero **Received By:**

Contact Person: Chuck Antle
US BANK TOWER
950 17TH ST STE 2200
DENVER, CO 80202

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine

Other

Description of Other Released Contaminant:

Heat from flare is believed to have started grass fire.

Inspected: **Written Report Received:** 11/1/2016 **Clean Up Concluded:** 10/28/2016

Risk Evaluation:

Fire hazard.

Areal Extent:

An estimated area of 2' X 15' outside of the lease boundary was affected.

Potential Environmental Impacts:

An estimated area of 2' X 15' outside of the lease boundary was affected.

Action Taken or Planned:

Ensure flares are operated withing capacity specifications.

Wastes Disposal Location: NA

Agencies Involved:

Updates

Date: 10/30/2016 **Status:** Reviewed - Follow-up Required

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire at site was not contained on location according to the report. Follow-up is necessary to confirm no off-site impact other than fire damage.

Date: 11/4/2016 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

11/2/2016, on location. Met site personnel. Incident appears to have occurred next to group of flares on SW part of wellpad. Scorched area matching incident description to the south of the flares, with burnt area approximately half on/half off the wellpad lease. Scorched grass and wellpad fence appear to be the only damage. No staining visible. No further follow-up required at this time.